

**1999 Ferrari F355 NHTSA Recall ID Number: 00V064000**

**Recall Date:** MAR 02, 2000

**Component:** SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:HOSES, LINES/PIPING, AND FITTINGS

**Potential Units Affected:** 477

**Summary:** VEHICLE DESCRIPTION: PASSENGER VEHICLES EQUIPPED WITH BOSCH BRAKING SYSTEM. BRAKE FLUID RESERVOIR HOSES MAY NOT BE RESISTANT TO BRAKE FLUID, WHICH COULD CAUSE FAILURE OF THE HOSES.

**Consequence:** SHOULD A HOSE FAILURE OCCUR, THE BRAKE FAILURE LIGHT WOULD LIGHT UP, FOLLOWED BY LOSS OF VEHICLE BRAKING EFFICIENCY.

**Remedy:** DEALERS WILL INSPECT THE HOSES AND, IF REQUIRED, INSTALL NEW HOSES THAT ARE RESISTANT TO BRAKE FLUID.

**Notes:** FERRARI NORTH AMERICA, 20

**1995 Ferrari F355 Berlinetta NHTSA Recall ID Number: 95V079000**

**Recall Date:** APR 20, 1995

**Component:** COMMUNICATIONS:HORN ASSEMBLY

**Potential Units Affected:** 211

**Summary:** THE INTERNATIONAL HORN EMBLEM IS MISSING FROM THE LEATHER STEERING WHEEL COVER. THIS DOES NOT MEET THE REQUIREMENTS FOR FMVSS NO. 101, "CONTROLS AND DISPLAYS."

**Consequence:** CONSEQUENCE OF NON-COMPLIANCE: THIS CONDITION CAN CAUSE INABILITY TO WARN OTHER DRIVERS IN A CRASH SITUATION, AND RESULT IN VEHICLE DAMAGE AND INCREASED RISK OF INJURY.

**Remedy:** DEALERS WILL STAMP THE STEERING WHEEL WITH AN ELECTRICALLY HEATED TOOL ON THE LEFT AND RIGHT SPOKE OF THE STEERING WHEEL.

**Notes:** FERRARI NORTH AMERICA,