

1979 Ferrari 308 GTB NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,

1979 Ferrari 308 GTS NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,

1978 Ferrari 308 GTB NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,

1978 Ferrari 308 GTS NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA

1977 Ferrari 308 GTB NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,

1977 Ferrari 308 GTS NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,

1976 Ferrari 308 GTB NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL

CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,

1975 Ferrari 308 GTB NHTSA Recall ID Number: 79V263000

Recall Date: OCT 17, 1979

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Units Affected: 2570

Summary: VEHICLES DO NOT CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 301, "FUEL SYSTEM INTEGRITY". THE FUEL HOSES CONNECTING THE DUAL GAS TANKS MAY FAIL DUE TO ENVIRONMENTAL CONDITIONS. THIS COULD CAUSE A GASOLINE LEAK BENEATH THE VEHICLE.

Consequence:

Remedy: DEALERS WILL REPLACE DEFECTIVE HOSES FREE OF CHARGE.

Notes: FERRARI NORTH AMERICA,