

**1988 Ferrari 328 GTB NHTSA Recall ID Number: 89V111000**

**Recall Date:** JUL 05, 1989

**Component:** SUSPENSION:FRONT:CONTROL ARM:LOWER ARM

**Potential Units Affected:** 1331

**Summary:** FRONT LOWER SUSPENSION ARM FORKS COULD DEFORM AFTER SUBSTANTIAL IMPACTS, SUCH AS IN AN ACCIDENT.

**Consequence:** THIS COULD RESULT IN EVENTUAL COLLAPSE OF THE SUSPENSIONARM WITH IMPAIRED HANDLING, WHICH COULD RESULT IN AN ACCIDENT.

**Remedy:** REPLACE FOUR FRONT LOWER SUSPENSION ARM FORKS WITH FORKS OF A GREATER THICKNESS.

**Notes:** FERRARI NORTH AMERICA

**1988 Ferrari 328 GTS NHTSA Recall ID Number: 89V111000**

**Recall Date:** JUL 05, 1989

**Component:** SUSPENSION:FRONT:CONTROL ARM:LOWER ARM

**Potential Units Affected:** 1331

**Summary:** FRONT LOWER SUSPENSION ARM FORKS COULD DEFORM AFTER SUBSTANTIAL IMPACTS, SUCH AS IN AN ACCIDENT.

**Consequence:** THIS COULD RESULT IN EVENTUAL COLLAPSE OF THE SUSPENSIONARM WITH IMPAIRED HANDLING, WHICH COULD RESULT IN AN ACCIDENT.

**Remedy:** REPLACE FOUR FRONT LOWER SUSPENSION ARM FORKS WITH FORKS OF A GREATER THICKNESS.

**Notes:** FERRARI NORTH AMERICA,

**1987 Ferrari 328 GTB NHTSA Recall ID Number: 89V111000**

**Recall Date:** JUL 05, 1989

**Component:** SUSPENSION:FRONT:CONTROL ARM:LOWER ARM

**Potential Units Affected:** 1331

**Summary:** FRONT LOWER SUSPENSION ARM FORKS COULD DEFORM AFTER SUBSTANTIAL IMPACTS, SUCH AS IN AN ACCIDENT.

**Consequence:** THIS COULD RESULT IN EVENTUAL COLLAPSE OF THE SUSPENSIONARM WITH IMPAIRED HANDLING, WHICH COULD RESULT IN AN ACCIDENT.

**Remedy:** REPLACE FOUR FRONT LOWER SUSPENSION ARM FORKS WITH FORKS OF A GREATER THICKNESS.

**Notes:** FERRARI NORTH AMERICA

**1987 Ferrari 328 GTS NHTSA Recall ID Number: 89V111000**

**Recall Date:** JUL 05, 1989

**Component:** SUSPENSION:FRONT:CONTROL ARM:LOWER ARM

**Potential Units Affected:** 1331

**Summary:** FRONT LOWER SUSPENSION ARM FORKS COULD DEFORM AFTER SUBSTANTIAL IMPACTS, SUCH AS IN AN ACCIDENT.

**Consequence:** THIS COULD RESULT IN EVENTUAL COLLAPSE OF THE SUSPENSIONARM WITH IMPAIRED HANDLING, WHICH COULD RESULT IN AN ACCIDENT.

**Remedy:** REPLACE FOUR FRONT LOWER SUSPENSION ARM FORKS WITH FORKS OF A GREATER THICKNESS.

**Notes:** FERRARI NORTH AMERICA,

#### **1986 Ferrari 328 GTB NHTSA Recall ID Number: 86V161000**

**Recall Date:** DEC 11, 1986

**Component:** ENGINE AND ENGINE COOLING:COOLING SYSTEM:HOSE

**Potential Units Affected:** 550

**Summary:** THE FLEXIBLE OIL HOSES FOR THE ENGINE OIL RADIATOR COULD LEAK ENGINE OIL DUE TO INSUFFICIENT CLAMPING OF THE METAL CONNECTORS TO FLEXIBLE PORTION OF OIL HOSE. CONSEQUENCE OF DEFECT: LACK OF LUBRICATION COULD CAUSE SEVERE ENGINE DAMAGE; OIL LEAKAGE COULD RESULT IN AN ENGINE FIRE.

**Consequence:**

**Remedy:** REPLACE LOWER AND UPPER HOSES CONNECTING ENGINE OIL RADIATOR WITH IMPROVED HOSES. ALSO, UPDATE OIL PRESSURE REGULATING VALVE ASSEMBLY.

**Notes:** FERRARI NORTH AMERICA,

#### **1986 Ferrari 328 GTB NHTSA Recall ID Number: 86V162000**

**Recall Date:** DEC 11, 1986

**Component:** FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

**Potential Units Affected:** 588

**Summary:** FLEXIBLE RUBBER HOSE FOR RETURN OF FUEL TO RIGHT SIDE FUEL TANK MAY CHAFE IF POSITIONED TOO CLOSE TO METALLIC DISCHARGE CONNECTOR OF AIR CONDITIONER COMPRESSOR. CONSEQUENCE OF DEFECT: FUEL LEAKAGE COULD OCCUR CREATING A FIRE POTENTIAL.

**Consequence:**

**Remedy:** REPOSITION FLEXIBLE FUEL HOSE; REPLACE IF HOSE SHOWS ABRASION OR DAMAGE.

**Notes:** FERRARI NORTH AMERICA,

#### **1986 Ferrari 328 GTB NHTSA Recall ID Number: 89V111000**

**Recall Date:** JUL 05, 1989

**Component:** SUSPENSION:FRONT:CONTROL ARM:LOWER ARM

**Potential Units Affected:** 1331

**Summary:** FRONT LOWER SUSPENSION ARM FORKS COULD DEFORM AFTER SUBSTANTIAL IMPACTS, SUCH AS IN AN ACCIDENT.

**Consequence:** THIS COULD RESULT IN EVENTUAL COLLAPSE OF THE SUSPENSIONARM WITH IMPAIRED HANDLING, WHICH COULD RESULT IN AN ACCIDENT.

**Remedy:** REPLACE FOUR FRONT LOWER SUSPENSION ARM FORKS WITH FORKS OF A GREATER THICKNESS.

**Notes:** FERRARI NORTH AMERICA,

**1986 Ferrari 328 GTS NHTSA Recall ID Number: 86V161000**

**Recall Date:** DEC 11, 1986

**Component:** ENGINE AND ENGINE COOLING:COOLING SYSTEM:HOSE

**Potential Units Affected:** 550

**Summary:** THE FLEXIBLE OIL HOSES FOR THE ENGINE OIL RADIATOR COULD LEAK ENGINE OIL DUE TO INSUFFICIENT CLAMPING OF THE METAL CONNECTORS TO FLEXIBLE PORTION OF OIL HOSE. CONSEQUENCE OF DEFECT: LACK OF LUBRICATION COULD CAUSE SEVERE ENGINE DAMAGE; OIL LEAKAGE COULD RESULT IN AN ENGINE FIRE.

**Consequence:**

**Remedy:** REPLACE LOWER AND UPPER HOSES CONNECTING ENGINE OIL RADIATOR WITH IMPROVED HOSES. ALSO, UPDATE OIL PRESSURE REGULATING VALVE ASSEMBLY.

**Notes:** FERRARI NORTH AMERICA,

**1986 Ferrari 328 GTS NHTSA Recall ID Number: 86V162000**

**Recall Date:** DEC 11, 1986

**Component:** FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

**Potential Units Affected:** 588

**Summary:** FLEXIBLE RUBBER HOSE FOR RETURN OF FUEL TO RIGHT SIDE FUEL TANK MAY CHAFE IF POSITIONED TOO CLOSE TO METALLIC DISCHARGE CONNECTOR OF AIR CONDITIONER COMPRESSOR. CONSEQUENCE OF DEFECT: FUEL LEAKAGE COULD OCCUR CREATING A FIRE POTENTIAL.

**Consequence:**

**Remedy:** REPOSITION FLEXIBLE FUEL HOSE; REPLACE IF HOSE SHOWS ABRASION OR DAMAGE.

**Notes:** FERRARI NORTH AMERICA,

**1986 Ferrari 328 GTS NHTSA Recall ID Number: 89V111000**

**Recall Date:** JUL 05, 1989

**Component:** SUSPENSION:FRONT:CONTROL ARM:LOWER ARM

**Potential Units Affected:** 1331

**Summary:** FRONT LOWER SUSPENSION ARM FORKS COULD DEFORM AFTER SUBSTANTIAL IMPACTS, SUCH AS IN AN ACCIDENT.

**Consequence:** THIS COULD RESULT IN EVENTUAL COLLAPSE OF THE SUSPENSION ARM WITH IMPAIRED HANDLING, WHICH COULD RESULT IN AN ACCIDENT.

**Remedy:** REPLACE FOUR FRONT LOWER SUSPENSION ARM FORKS WITH FORKS OF A GREATER THICKNESS.

**Notes:** FERRARI NORTH AMERICA,