

**1975 Ferrari Dino 308 GT4 NHTSA Recall ID Number: 77V070000**

**Recall Date:** MAY 10, 1977

**Component:** SUSPENSION:REAR

**Potential Units Affected:** 507

**Summary:** THE INNER BUSHINGS OF THE ARTICULATED JOINTS OF THE REAR SUSPENSION MAY RUST DUE TO ADVERSE ENVIRONMENTAL CONDITIONS. RUST MAY CAUSE THE SUSPENSION TO JAM.

**Consequence:**

**Remedy:** THE DEALER WILL REPLACE THE ORIGINAL BUSHINGS WITH INNER CHROME-PLATED BUSHINGS. THE CHROME PLATING WILL NOT BE SUSCEPTIBLE TO RUST.

**Notes:** FERRARI NORTH AMERICA,